

P
PIERRE LANNIER
PARIS

NOTICE D'EMPLOI
N°513

MONTRES
AUTOMATIQUES

Les montres à mouvement automatique se remontent elles-mêmes par le mouvement du poignet.

▪ **Mise en service:**

Avant de porter la montre ou suite à une période d'inactivité, il est nécessaire de la remonter manuellement. Pour cela, maintenir la couronne en position normale puis tourner dans le sens des aiguilles d'une montre de 15 à 20 fois.

Suite à cette manipulation, le mouvement se remonte automatiquement grâce aux mouvements du poignet.

Attention : En cas de faible activité, la montre ne pourra pas se remonter suffisamment, pouvant entraîner des retards, avances ou même l'arrêt de la montre.

Dans ce cas, il vous faudra compenser par un remontage manuel.



P
PIERRE LANNIER
PARIS

INSTRUCTION
MANUAL
N°513

AUTOMATIC WATCHES

Automatic watches are wound automatically as a result of natural movements of the wrist.

•**Starting:**

It is necessary to wind the watch manually after not being used for a period of time. To do so, pull out the crown and turn it clockwise 15-20 times. After that the watch will wind itself automatically thanks to the natural motion of the user's wrist.

Caution: If the watch is not worn for a few days, it will not be able to wind itself. This may also cause the watch to run slow, fast or to stop. In this case the watch will have to be wound manually (as explained above).



MKT11.17